


Fitup

Fitup Create





sync the details to the web



To **create Fitup** request,do the following


1. Take **offline**data for **Master Data-FITUP/WeldVI.**
2. Click **Fitup Create** menu
3. Here joints listed to create the **Fitup**
4. Select the **joints**
5. Enable **Fitup completed** toggle button
6. Click **Save**


Fitup request created successfully.

Click **Sync** button at the top to sync data to web manually.Otherwise it will be synced automatically.

Fitup Inspection

For fitup inspection,do the following steps


Project
Offline
Equipment
Pending
Pressure Vessel - Fitup/Visual
MIR
MTR
Fitup Create
WeldVI Create
NDT Request Add
Inspection - Pressure Vessel
Weld Spot Check
Fitup
WeldVI
NDT Report
Joint Number
LS
WPS : ROS-WPS-01
A12
Fitup-Date :
14/07/2025
Location
ALL



1. Take **offline** data for **Fitup Inspection.**
2. Click **Fitup** menu in inspection
3. Here fitup inspection created joints listed
4. **Select** the joint
5. Enable **inspection** toggle button
6. Select **heat number 1**and **heat number 2** and **Result**
7. Click **Save** button placed at the bottom

Fitup inspection updated successfully.

Click **Sync** button at the top to sync data to web.Otherwise it will be synced automatically.

Revision #2
Created 1 June 2026 12:38:46 by Shybin
Updated 1 June 2026 13:43:15 by Shybin