Production - Fitup Request & QA Inspection


Production shall make the fitup request using the system in a very simple manner.

The production users has limited access to the system.

They have read only access to drawing, joints, ITP, weld Map etc.

When the fitup is completed, they need to call for inspection to QA/QC. It can be done in a very simpler manner in cuteQM.

Navigate to Fitup in menu and in the list of joints choose the joint which you want to call for inspection, click Edit.



Click the button Fit-Up Completed.

The Fit-Up date will appear automatically todays date.

Optionally choose Tack Welder

Click Save.

This will send a notification to the project QA/QC inspector for inspection.

Revision #2
Created 27 August 2025 05:05:03 by Jnaveen
Updated 27 August 2025 08:07:50 by Jnaveen