

Weld Visual

WeldVI Create



The **WeldVI create** tab helps you to create weld visual request in mobile and sync the details to the web application.

To create Weld visual request,do the following steps

1. Click **weldvi create** menu
2. **Select** the joint
3. Enable the toggle button as **Completed**
4. Click **+ icon** to add welder details
5. Click **Save** button

Weldvi request created successfully.

Click **Sync** button at the top to sync data to web. Otherwise it will be synced automatically.





WeldVI Inspection

For **weld visual inspection**,do the following steps.

1. Click **Weldvi** menu in inspection
2. **Select** the joint
3. Enable the **Inspection** toggle button
4. Select the result as **Accepted**
5. Click **Save**

WeldVI inspection updated successfully.

Click **Sync** button at the top to sync data to web.Otherwise it will be synced automatically.



Revision #2

Created 1 June 2026 14:05:02 by Shybin

Updated 1 June 2026 14:12:34 by Shybin