

# Production - Fitup Request & QA Inspection


Production shall make the fitup request using the system in a very simple manner.

The production users has limited access to the system.

They have read only access to drawing, joints, ITP, weld Map etc.

When the fitup is completed, they need to call for inspection to QA/QC. It can be done in a very simpler manner in cuteQM.

Navigate to Fitup in menu and in the list of joints choose the joint which you want to call for inspection, click Edit.

	67	J1007	107	112	<input checked="" type="checkbox"/>	support	07/02/2025 08:54 AM
	68	J1008	101	101	<input type="checkbox"/>		

**Fit-up**

Fit-Up Completed ?

Location

By jnaveen

Fit-Up Date

Tack Weld

Comments

Save Cancel

Click the button Fit-Up Completed.

The Fit-Up date will appear automatically today's date.

Optionally choose Tack Welder

Click Save.

This will send a notification to the project QA/QC inspector for inspection.

---

Revision #2

Created 27 August 2025 05:05:03 by Jnaveen

Updated 27 August 2025 08:07:50 by Jnaveen