


RFI FITUP INSPECTION

7.0 RFI FITUP INSPECTION

The **RFI FITUP INSPECTION** tab helps you to check and approve the RFI fitup request raised in the web application, by adding and updating your inspection details. This RFI fitup inspection feature automatically updates and synchronizes your inspection details with the RFI Fitup report that is uploaded in the web application.

 image.1651720450596.png


 image.1651720463465.png **Note:** when you click the **RFI FITUP INSPECTION** tab in the dashboard, the **RFI Fitup Inspection** page displays a list of reports corresponding to today and previous day. However, if you want to view the reports for other dates, you must navigate to the **TAKE OFFLINE DATA** option. (See "[TAKE OFFLINE DATA](#)" for more details.)

1. Tap **RFI FITUP INSPECTION**. See Fig 2.3.

The **RFI Fitup Inspection** page opens with a list of reports for the selected date.

 image.1651720485651.png

Figure 8.1 RFI Fitup Inspection page

 image.1651720504210.png **Tip:** 1. You can configure displaying of the number of reports per page by selecting **10**, **25**, **50** or **100**, accordingly.

2. If you want to filter one report among the list of reports, you must enter the report number, inspection date or location details in the respective boxes given in the **RFI Fitup Inspection** page.

The **RFI Fitup Inspection** page contains multiple fields such as **Report Number, Inspection Date, Location, Result, Signature, Attach, Print, and Sync**. (See the topic "[The MIR page contains the following fields](#)" for more details about each field in the **RFI Fitup Inspection** page.)

To add your RFI fitup inspection result

1. Once you find out the report where you need to add your inspection details, tap

 image.1651720579098.png

(**Result** icon) to add your inspection results, See Fig 8.1.

The **Result** page opens with a list of reports with the material details. Each report shows material specifications such as system details, line numbers, heat numbers, spool number, components name, MIR details, etc.

[image-1651720635861.png](#)

Image not found or type unknown

2. In the **Remarks** box, type your remarks if any.
3. Check and reenter the heat numbers of the respective report where you want to add your inspection details.
4. In the **Result** box, tab and choose **Pending, Accepted, Rejected or Cancelled** from a drop-down list based on your inspection details.
5. In the **Remarks** box, type your remarks if any.
6. If you want to add any photo with the report, do the following steps,

[image-1651720742125.png](#)

- a. Tab **Image not found** (photo capturing icon).

Your mobile camera starts to capture the image.

- b. Capture the material part, which you want to add.

The captured images are automatically saved in the image's gallery.

[image-1651720828710.png](#)

- c. Tab **Image not found** (**Images** icon) to view the captured images.

[image-1651721655159.png](#)

Note: The captured images are automatically updated with the web application.

7. Tab **Save**.

To add your signature

Once you have saved your inspection results, the **Result** page automatically redirects you into the **Signature** page. Otherwise, tap

[image-1051721007577.png](#)

Image not found (Signature icon), See Fig 8.1.

To know how to add your signature, see the topic "[To add your signature](#)".

Revision #4

Created 5 May 2022 03:12:09

Updated 10 December 2024 05:43:41 by Shybin